

Rapid Rural Reconnaissance Report for

Vashon – Maury Island

TABLE OF CONTENTS

<i>Title</i>	<i>Page No.</i>
Acknowledgements	i
Acronyms, Abbreviations, and Terms.....	iii
Table of Contents	v
Summary	S-1
Scope of Analysis	S-1
Basin Description	S-1
Assessment of Subbasins	S-2
Groundwater	S-2
Nearshore Habitat.....	S-2
Recommended Actions	S-3
Further Actions Needed.....	S-5
Public Education.....	S-5
Coordination with Other Agencies.....	S-5
Updates to Reconnaissance Report	S-5
1. Introduction	1-1
1.1 Purpose and Project Description.....	1-1
1.2 Study Area.....	1-1
1.3 Project Goals.....	1-1
1.4 Project Approach.....	1-2
1.4.1 Characterization.....	1-2
1.4.2 Action Plan.....	1-2
1.5 Report Contents	1-3
1.6 Public Involvement.....	1-3
2. Basin Characteristics	2-1
2.1 Drainage Basin	2-1
2.1.1 Subbasin Boundaries and Characteristics	2-1
2.1.2 Stream Reaches	2-3
2.2 Land Cover Analysis	2-3
2.2.1 Land Cover.....	2-3
2.2.2 Soils.....	2-5
2.2.3 Topography	2-5
2.2.4 GIS Analysis.....	2-5
2.2.5 Riparian Corridor Land Cover Analysis	2-11
2.3 Conclusions and Recommendations	2-11

3. Hydrology	3-1
3.1 Hydrologic Modeling Method.....	3-1
3.1.1 Software Used.....	3-1
3.1.2 Analyses Conducted.....	3-1
3.1.3 Rainfall Variation	3-1
3.1.4 Land Coverage and Impervious Area	3-2
3.1.5 Channel Characteristics	3-2
3.2 Modeling Results.....	3-2
3.2.1 Mean Daily Flow	3-2
3.2.2 Flow Duration.....	3-3
3.2.3 Low Flow Characteristics	3-6
3.2.4 Flow Frequency Analysis.....	3-6
3.3 Qualitative Analysis of Future Buildout Conditions.....	3-8
3.4 Conclusions and Recommendations	3-8
4. Groundwater.....	4-1
4.1 Groundwater Flow System.....	4-1
4.1.1 Hydrostratigraphy	4-1
4.1.2 Groundwater Flow	4-3
4.2 Groundwater Conditions.....	4-5
4.2.1 Information Sources.....	4-5
4.2.2 Groundwater Quality	4-6
4.2.3 Groundwater Supply	4-6
4.2.4 Management Programs and Regulatory Agencies	4-6
4.3 Stormwater Management.....	4-7
4.4 Conclusions and Recommendations	4-7
5. Geomorphology	5-1
5.1 EIA and Forest Cover Analysis	5-1
5.2 Hydrologic Analysis - Judd Creek and Shinglemill Creek...	5-1
5.3 Soils Erosion Potential.....	5-7
5.4 Landslides	5-7
5.5 Conclusions and Recommendations	5-9
6. Water Quality	6-1
6.1 Existing Water Quality Data	6-1
6.1.1 Water Quality Standards.....	6-1
6.1.2 Water Quality Sampling Data	6-2
6.1.3 Biotic Integrity.....	6-8
6.2 Potential Pollutant Sources.....	6-8
6.3 Conclusions and Recommendations	6-12
7. Stream Habitat	7-1
7.1 Island-Wide Habitat Conditions.....	7-1

7.1.1	Land Use	7-1
7.1.2	Stream Habitat Conditions	7-1
7.1.3	Riparian Habitat and LWD	7-2
7.1.4	Habitat Limiting Factors	7-2
7.2	Stream Habitat Classification Methods	7-10
7.2.1	General Characteristics	7-10
7.2.2	Subbasin Alteration	7-11
7.2.3	Benthic Index of Biotic Integrity	7-13
7.2.4	Subbasin Summary	7-14
7.3	Judd Creek Subbasin 1 Stream Habitat Classification	7-21
7.3.1	General Characteristics	7-21
7.3.2	Subbasin Alteration	7-21
7.3.3	Benthic Biodiversity	7-22
7.3.4	Subbasin 1 Summary	7-23
7.4	Judd Creek Subbasin 2 Stream Habitat Classification	7-24
7.4.1	General Characteristics	7-24
7.4.2	Subbasin Alteration	7-24
7.4.3	Benthic Biodiversity	7-25
7.4.4	Subbasin 2 Summary	7-26
7.5	Judd Creek Subbasin 3 Stream Habitat Classification	7-27
7.5.1	General Characteristics	7-27
7.5.2	Subbasin Alteration	7-27
7.5.3	Benthic Biodiversity	7-29
7.5.4	Subbasin 3 Summary	7-29
7.6	Shinglemill Subbasin 1 Stream Habitat Classification	7-30
7.6.1	General Characteristics	7-30
7.6.2	Subbasin Alteration	7-30
7.6.3	Benthic Biodiversity	7-32
7.6.4	Subbasin Summary	7-32
7.7	Shinglemill Subbasin 2 Stream Habitat Classification	7-34
7.7.1	General Characteristics	7-34
7.7.2	Subbasin Alteration	7-34
7.7.3	Benthic Biodiversity	7-35
7.7.4	Subbasin Summary	7-35
7.8	Shinglemill Subbasin 3 Stream Habitat Classification	7-36
7.8.1	General Characteristics	7-36
7.8.2	Subbasin Alteration	7-36
7.8.3	Benthic Biodiversity	7-37
7.8.4	Subbasin Summary	7-37
7.9	Shinglemill Subbasin 4 Stream Habitat Classification	7-38
7.9.1	General Characteristics	7-38
7.9.2	Subbasin Alteration	7-38
7.9.3	Benthic Biodiversity	7-40

7.9.4 Subbasin Summary	7-40
7.10 Overall Basin Summaries.....	7-40
7.10.1 Judd Creek Basin.....	7-40
7.10.2 Shinglemill Creek Basin	7-41
7.11 Conclusions and Recommendations	7-41
7.11.1 Fish Passage	7-41
7.11.2 Bulkheads	7-42
7.11.3 Water Diversions	7-42
7.11.4 Riparian Habitat Restoration.....	7-42
7.11.5 Shinglemill Creek Mass Wasting	7-42
7.11.6 Stream Channelization	7-42
7.11.7 Protection of Natural Hydrology	7-42
7.11.8 Data Needs.....	7-43
8. Nearshore Habitat.....	8-1
8.1 General Description of Vashon's Nearshore.....	8-1
8.2 Summary of Available Information about the Nearshore	8-2
8.2.1 ShoreZone Inventory, 1994-2000	8-2
8.2.2 Various Studies, 1998-2000	8-2
8.2.3 Washington Trout Stream Mouth Study, 2000	8-2
8.2.4 SONR, 2001	8-3
8.2.5 Rapid Shoreline Inventory, 2001-2002	8-3
8.2.6 Vashon-Maury Island Beach Seining, 2001-2002.....	8-3
8.2.7 WRIA Reports, 2001-2005.....	8-3
8.3 Near-Term Future of Assessment of the Nearshore	8-3
8.3.1 WRIA 9 Green-Duwamish River and Vashon Island Watersheds	8-3
8.3.2 The Puget Sound Nearshore Ecosystem Restoration Project (PSNERP).....	8-4
8.4 Conclusions and Recommendations	8-4
8.4.1 SONR Recommendations.....	8-4
8.4.2 PSNERP Recommendations	8-6
8.4.3 Additional Recommendations	8-7
9. Drainage and Erosion Problem Analysis	9-1
9.1 Approach to Identifying Drainage Problems.....	9-1
9.1.1 Drainage Complaint Review	9-1
9.1.2 Hydrologic Modeling Assessment	9-2
9.2 Identifying the Existing Drainage Network	9-2
9.3 Conclusions and Recommendations	9-2
10. Basin Summary and Vulnerability Analysis.....	10-1
10.1 Summary of Findings.....	10-1

10.1.1 Groundwater	10-1
10.1.2 Geomorphology	10-1
10.1.3 Water Quality	10-2
10.1.4 Stream Habitat	10-3
10.1.5 Nearshore Habitat	10-4
10.1.6 Drainage Problems.....	10-4
10.2 Watershed Vulnerability Analysis	10-4
11. Recommended Actions	11-1
11.1 Recommended Actions.....	11-1
11.1.1 Project Selection.....	11-1
11.1.2 Project Ranking	11-1
11.1.3 Cost Estimating	11-1
11.2 Island-Wide Recommendations	11-1

Appendices

- A. CIP Project Forms
- B. Shinglemill Creek Modeling
- C. Judd Creek Modeling
- D. Water Quality Data
- E. Drainage Complaints
- F. Vashon And Maury Island Extract From State Of The Nearshore Ecosystem
- G. Vulnerability Analysis
- H. Landslides
- I. References

LIST OF TABLES

No.	Title	Page No.
S-1	Ranked Recommended Actions.....	S-3
S-2	Unranked Actions	S-4
1-1	Main Elements of the Basin Characterization Process.....	1-2
1-2	Typical Activities Included in Action Plan	1-4
2-1	Vashon-Maury Island Subbasin Areas	2-1
2-2	Judd and Shinglemill Creek RCHRES Characteristics.....	2-4
2-3	Land Cover Type Equivalency for HSPF.....	2-6
2-4	Effective Impervious Area Assignment.....	2-7
2-5	Effective Impervious Area by Zoning Code	2-8
2-6	Soil Type Transformation for HSPF.....	2-8
2-7	Slope Category Equivalency for HSPF	2-9
2-8	Number of Unique Land Surface Types.....	2-9
2-9	Land Surface Types for HSPF.....	2-9
2-10	Predeveloped Land Surface Summary by Subbasin	2-10
2-11	Existing (2001) Land Surface Summary by Subbasin.....	2-10
2-12	Future Buildout Land Surface Summary by Subbasin.....	2-11
2-13	Existing (2001) Land Surface Summary by Subbasin for 200-Foot Riparian Corridor	2-12
3-1	Mean Daily Flow Rate, cfs	3-3
3-2	Judd Creek RCHRES 100 Hourly Flow Rate Duration Analysis	3-4
3-3	Mean 7-Day Low Flow	3-6
3-4	Flow Frequency Analysis.....	3-7
3-5	USGS Flood Frequency Analysis, cfs.....	3-7
3-6	Subbasin Characteristics to Assess Future Flows	3-8
5-1	Existing and Future Forest Cover and Effective Impervious Area..	5-2
5-2	Comparison of Q10pre and Q2post Flows for Judd and Shinglemill Creeks	5-6
5-3	Channel Stability for Judd and Shinglemill Creek Subbasins.....	5-6
5-4	Soil Type Erosion Potential	5-14
6-1	Class AA Criteria for Freshwater Streams	6-2
6-2	East Vashon Basin Sampling Sites	6-3
6-3	Judd Creek Basin Sampling Sites.....	6-4
6-4	Shinglemill Creek Basin Sampling Sites.....	6-5
6-5	West Vashon Basin Sampling Sites.....	6-6

6-6 Maury Island Sampling Sites	6-7
6-7 Potential Pollutant Sources	6-10
7-1 Stream Habitat Conditions and Fish Species Present for Vashon-Maury Island Streams	7-3
7-2 Summary of Habitat Limiting Factors for Vashon Island Streams Identified in the WRIA 9 Report	7-5
7-3 Subbasin Alteration Matrix.....	7-13
7-4 Interpretation of B-IBI Total Scores.....	7-14
7-5 The I-IBI Scoring Method (from King County 2002).....	7-15
7-6 Field Assessment Criteria and Thresholds (from R2 Resources 2001)	7-16
7-7 Pre-Developed and Post-Developed 2-Year Flows and Ratio; RCHRES Segment 100 and 200 in Judd Creek Subbasin 1.....	7-22
7-8 Subbasin Alteration Matrix for Judd Creek Subbasin 1	7-22
7-9 B-IBI Metric Scores for Judd Creek at SW 216 th Street.....	7-23
7-10 Pre-Developed and Post-Developed 2-Year and Ratio; RCHRES Segment 300 in Judd Creek Subbasin 2.....	7-25
7-11 Subbasin Alteration Matrix for Judd Creek Subbasin 2	7-26
7-12 B-IBI Metric Scores for Judd Creek at Cemetery Road.....	7-26
7-13 Pre-Developed and Post-Developed 2-Year Flows and Ratio; RCHRES Segment 400 in Judd Creek Subbasin 3.....	7-28
7-14 Subbasin Alteration Matrix for Judd Creek Subbasin 3	7-29
7-15 B-IBI Metric Scores for Judd Creek at Cemetery Road in Subbasin 3.....	7-29
7-16 Pre-Developed and Post-Developed 2-Year Flows and Ratio; RCHRES Segment 100 in Shinglemill Subbasin 1	7-31
7-17 Subbasin Alteration Matrix for Shinglemill Subbasin 1	7-32
7-18 B-IBI Metric Scores for Shinglemill Creek at SW Cedarhurst Road	
7-33	
7-19 Subbasin Alteration Matrix for Shinglemill Subbasin 2	7-35
7-20 Pre-Developed and Post-Developed 2-Year Flows and Ratio; RCHRES Segment 300 in Shinglemill Subbasin 3.....	7-36
7-21 Subbasin Alteration Matrix for Shinglemill Subbasin 3	7-37
7-22 Pre-Developed and Post-Developed 2-Year Flows and Ratio; RCHRES Segment 400 in Shinglemill Subbasin 4.....	7-39
7-23 Subbasin Alteration Matrix for Shinglemill Subbasin 4	7-39
9-1 Summary of Drainage Complaints on Vashon-Maury Island 1990-2002.....	9-2
9-2 Drainage Problems Identified for Possible Improvement Projects..	9-3

10-1 Results of Judd Creek and Shinglemill Creek Vulnerability Analysis	
10-5	
10-2 Results of Modified Vulnerability Analysis 10 Highest Ranking Creeks.....	10-6
11-1 Recommended Actions	<i>follows page 11-2</i>
11-2 Ranked Recommended Actions.....	11-4
11-3 Unranked Actions	11-5

LIST OF FIGURES

<i>No.</i>	<i>Title</i>	<i>Page No.</i>
1-1	Vashon Island – Creek Basins Delineations.....	<i>follows page 1-1</i>
2-1	Vashon Island – Subbasins and Stream Reaches.....	<i>follows page 2-1</i>
2-2	Vashon Island – 2001 Land Cover Map.....	<i>follows page 2-3</i>
2-3	Judd Creek Graphic Representation of RCHRES Routing.....	2-4
2-4	Shinglemill Creek Graphic Representation of RCHRES Routing.....	2-4
2-5	Vashon Island – Zoning Map.....	<i>follows page 2-6</i>
2-6	Vashon Island – Soils Map.....	<i>follows page 2-6</i>
2-7	Vashon Island – Topographic Map.....	<i>follows page 2-6</i>
2-8	Vashon Island – 200 Foot Riparian Corridor	<i>follows page 2-11</i>
3-1	Judd Creek RCHRES 100 Flow Duration Comparison	3-5
3-2	Shinglemill Creek RCHRES 100 Flow Duration Comparison.....	3-5
4-1	Generalized Subsurface Profiles.....	<i>follows page 4-1</i>
4-2	Vashon-Maury Island Water Table	<i>follows page 4-1</i>
5-1	Percent Forest Cover and EIA Under Existing Conditions	5-2
5-2	Vashon Island – Basins at Risk to Stream Erosion and Instability.....	<i>follows page 5-5</i>
5-3	Historical, Current, and Future Channel Stability in Judd Creek Subbasin 1	5-7
5-4	Historical, Current, and Future Channel Stability in Judd Creek Subbasin 2	5-8
5-5	Historical, Current, and Future Channel Stability in Judd Creek Subbasin 3	5-9
5-6	Historical, Current, and Future Channel Stability in Shinglemill Creek Subbasin 1.....	5-10
5-7	Historical, Current, and Future Channel Stability in Shinglemill Creek Subbasin 2.....	5-11
5-8	Historical, Current, and Future Channel Stability in Shinglemill Creek Subbasin 3.....	5-12
5-9	Historical, Current, and Future Channel Stability in Shinglemill Creek Subbasin 4.....	5-13
6-1	Vashon Island – King County Sampling Stations.....	<i>follows page 6-2</i>

6-2 Sediment Sources Identified by Washington Trout.....	6-11
7-1 Vashon Island – Creek Basin Delineations	<i>follows page</i> 7-43
7-2 Vashon Island – Fish Barriers	<i>follows page</i> 7-43
7-3 Vashon Island – Channel Types.....	<i>follows page</i> 7-43
7-4 Vashon Island – Preliminary Habitat.....	<i>follows page</i> 7-43
11-1 Vashon Island – Ranked Capital Improvement Projects	<i>follows page</i>
11-2	
11-2 Sample Worksheet for Ranking Recommended Capital Improvement Projects.....	11-3